COMMENT REPORT

DATE:

10-7-07

COST CONTROL SERVICES

INSURED

Harmon, Ella & Smith, Chantel

INS CO:

State Farm Ins. Co.

POLICY# POLICY DATES: 18-EF-5554-7 8-29-05 - 06

LOSS LOCATION:

2225 - 22nd St. Lake Charles, LA 70601

DATE OF LOSS:

COMMENTS:

We have attached a Recap Sheet on the above-mentioned claim. It is a recap of the damages that the insured has incurred.

A.) The dwelling damage totaled \$120,401.20. We have shown the 10% depreciation on the total dwelling damage. The depreciation totals \$12,040.12, which makes the A.C.V. loss total \$108,361.08. With the \$1,000.00 deductible, which now makes the ACV claim \$107,361.08.

After deducting the original payment on the dwelling, that is \$15.517.72, it now makes the net A.C.V. supplement claim on the dwelling \$91,843.36.

We have written our estimate per the damage we found which was caused by the hurricane and according to things the insured pointed out to us as well as the engineer's report done by Charles Norman. We feel that our estimate is in line with what we found at the damage risk and the engineer's report.

B.) The A,P.S. damage totaled \$2,861.89 less 10% depreciation. The 10% depreciation makes the total \$286.19. The total A.P.S. loss is now in the amount of \$2,575.20. After deducting the original payment of \$1,700.93 on the A.P.S., the net A.C.V. claim is now \$874.77.

We have written our estimate under coverage A & B, but State Farm has put coverage A & B together. We separated the two, which is how it should be done. We feel



that our estimate is in line with the damage found at the risk.

General Comments:

I have reviewed the engineer's report and there are some items in it that I do not feel comfortable with, but I have included in the estimate everything that was cited in the his report.

Payment Breakdown: Dwelling \$91,843.36

A.P.S. \$ 874.77

TOTAL <u>\$92,718.13</u>

We recommend payment to the above named insured, Ella Harmon and Chantel Smith and Lundy & Davis, Attorneys at Law, in the amount of \$92,718.13. This payment can be mailed to the Law Office of Lundy & Davis, P. O. Box 3010, Lake Charles, LA. 70603-3010.

If there are any questions, please feel free to give us a call.

Kermith Sonnier, President

Cost Control Services, LLC 3611 Kirkman Street Lake Charles, LA 70607 (337) 474-1693 Business (337) 474-1694 Fax Recap Sheet

Date:

11-19-08

Insured's Name:

Harmon, Ella & Smith, Chantel

Insurance Company:

State Farm Ins.

Policy#:

18-EF-5554-7

Policy Dates:

8-29-05 - 06

Date of Loss:

9-24-05

Loss Location:

2225 - 22nd St. Lake Charles, LA 70601-7948

Coverage:

A: 221,400.00

Dwelling

C:

Personal Property

B: 22,140.00

APS

D:

A.L.E.

Damage	RC	Depreciation	ACV
Dwelling			
Loss & Damage per Detail Attached	120,401.20	: :	
Less Depreciation 10%	. :	12,040.12	
ACV Loss			108,361.08
Less Deductible			-1,000.00
ACV Claim			107,361.08
Less Previous Payments on Dwelling			-15,517.72
ACV Supplement Claim			91,843.36
APS			:
Loss & Damage per Detail Attached	2,861.89		
Less Depreciation 10%		-286.19	:
ACV Loss			2575.70
Less Previous Payments			-1,700.93
A.C.V Net Claim			874.77
	123,263.09	-12,326.31	
New ACV Supplement Claim			92,718.13

Kermith Sonnier Cost Control Services

Case 2:07-cv-01990-PM-KK Document 32-4 Filed 02/23/09 Page 4 of 31

Cost Control Sevices

Insured:

Harmon, Ella

Property:

2225 22nd st.

Lake Charles, LA 70601

Claim Number: 8-R556-392

Policy Number: 18-EF-5554-7

Type of Loss: Hurricane

Coverage

Deductible

Policy Limit

Dwelling

\$0.00

\$0.00

Date of Loss: Date Inspected: 9/24/2005

Date Received:

Date Entered:

10/1/2007 11:13 PM

Price Lisn

LALC2B53


Restoration/Service/Remodel

Estimate:

2225_22ND_ST

2225_22ND_ST

General Conditions



DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL	
Residental supervision - per hour	240.00 HR	0,00	63.31	15,194.40	
R&R Central air conditioning system	1.00 EA	189.98	4,025 63	4,215.61	
R&R Ductwork system - hot or cold air	1.00 EA	436.23	3,936.97	4,373.20	
R&R Blown-in instruction	2,500.00 SF	0.75	0.79	3,850:00	
Dumpster load - Approx. 40 yards, 7-8 tons of debris	2 00 EA	973.05	0.00	1,946.10	
Dump and landfill fees - (per ton)	4.00 EA	51.75	0.00	207.00	
Tarp - all purpose poly - per sq ft (labor and material)	2,400.00 SF	0.00	0.47	1,128.00	
Temporary toilet (per month)	4.00 MO	0.00	110.52	442.08	
Temporary Repars - per hour	40.00 HR	0.00	26.91	1,076.40	
Taxes, insurance permits & fees (Bid item)	1.00 EA	0.00	1,000.00	1,000.00	
10,000 watt generator (per month)	1.00 MO	0.00	97750	977.50	
Remove Trees From Structure as per bid	1.00 EA	5,275 10	0.00	5,275.10	
Additional Debris Removal Due to Location	2 00 EA	250.00	0.00	500.00	
Level slab /with supports	1 00 EA	0.00	4,500.00	4,500.00	

Totals: General Conditions 44,685.39

Exterior

Front Elevation

680.00 SF Walls

680.00 SF Walls & Ceiling

680.00 SF Walls & Ceiling

680.00 SF Long Wall


85.00 LF Ceil. Perimeter

DESCRIPTION	TION QNTY REMOVE		REPLACE	TOTAL	
R&R Column - round cast fiberglass - 8" diameter	16.00 LF	4.58	32.90	599.68	
R&R Soffit - wood	18.00 SF	0.24	3.98	75.96	
R&R Trim board - 1" x 8" - installed (fascia)	12.00 LF	0.35	4.38	56.76	
R&R Gutter / downspour - galvanized	38.00 LF	0.39	3.28	139.46	
R&R Sheathing - plywood - 3/8"	85.58 SF	0 44	1.17	137.79	
R&R Light fixture	1.00 EA	6.54	47.93	54.47	
R&R Crown molding - 3 1/4"	39 17 LF	0.53	3.09	141.80	
Paint column	16.00 LF	0.00	2.29	36.64	
Paint exterior fascia - i coat - wood, 6"- 8" wide	12.00 LF	0 00	1.12	13.44	
Paint exterior soffit - wood - 1 coat	18.00 SF	0.00	1.12	20.16	
Paint the surface area	85.58 SF	0.00	0.77	65.90	
Seal & paint crown molding	39.17 LF	0.00	1.02	39.95	
Prime & paint gutter / downspout	38.00 LF	0.00	1.26	47.88	
Mask and prep for paint	85.00 LF	0.00	1 03	87.55	

Totals: From Elevation 1,517.44

Right Elevation

Formula Elevation 26'7" x ... x 7'8"



283.56 SF Walls 283.56 SF Walls & Ceiling 283.56 SF Long Wall 29.17 LF Ceil, Perimeter


26.58 LF Floor Perimeter 283.56 SF Short Wall

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL	
R&R Crown molding - 3 1/4"	40.00 LF	0.53	3.09	144.80	
Paint exterior sascia - i coat - wood, 6"- 8" wide	40.00 LF	000	1.12	44.80	
Paint exterior soffit - wood - 1 coat	40.00 SF	0.00	1.12	4480	
Paint the surface area	85.58 SF	000	0.77	65.90	
Seal & paint crown molding	40.00 LF	0.00	1.04	41.60	
Mask and prep for paint	29.17 LF	0.00	1 03	30.05	

Totals: Right Elevation 371 95

Rear Elevation


LxWxH 0'0" x 0'0" x 8'0"



QNTY	REMOVE	REPLACE	TOTAL
120.00 SF	0.20	2.13	279.60
30.00 LF	1.47	4.22	170.70
240.00 SF	0.64	12.14	3,067.20
	120.00 SF 30.00 LF	120.00 SF 0.20 30.00 LF 1.47	120.00 SF 0.20 2.13 30.00 LF 1.47 4.22

Left Elevation

Formula Elevation 71'4" x ... x 7'8"



567.69 SF Walls 567.69 SF Walls & Ceiling 567.69 SF Long Wall 71.34 LF Ceil. Perimeter


71.33 LF Floor Perimeter 567.69 SF Short Wall

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL	
Paint exterior fascie - 1 coat - wood, 6"- 8" wide	134.00 LF	0 00	1 12	150.08	
Paint exterior soffit - wood - 1 coat	134.00 SF	0.00	1.12	150.08	
Paint the surface area	85.58 SF	0.00	0.77	65.90	
Seal & paint crown molding	134.00 LF	0.00	1.04	139.36	
Mask and prep for paint	71.34 LF	000	1.03	73.48	
	· · · · · · · · · · · · · · · · · · ·				

578.90 Totals: Left Elevation

Roof


LxWxH 0'0" x 0'0" x 8'0"



DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL	
R&R 3 tab - 25 yr. comp shingle roofing - w/out felt	39.30 SQ	43.71	108.33	5,975.17	
Roofing felt	39.30 SQ	0.00	22.43	881.50	
Ridge cap - composition shingles	140 50 LF	0.00	2.12	297.86	
R&R Roll rod™ng	2.79 SQ	33.97	52.66	241.70	
Roofing felt	2.79 SQ	$0.\overline{00}$	22.43	62.58	
R&R Rafters - 2x8	2,000.00 SF	0.75	1.97	5,440.00	
R&R Sheathing - p'ywood - 5/8"	2,000.00 SF	1.06	1.93	5,980.00	
R&R 2" x 4" famber bracing	500.00 EA	0.43	1.17	800.00	
R&R Labor to install joist - floor or ceiling - 2x10	800.00 LF	084	1.29	1,704.00	
R&R Flashing - pipe jack	6.00 EA	5.52	23.84	176.16	
R&R Ridge flashing	140.50 LF	1.13	4.64	810.69	
R&R Valley metal	66.00 LF	0.47	3.27	246.84	
R&R Chimney flashing - (32" x 60")	1.00 EA	19.63	400.00	419.63	
R&R Drip edge	347.00 LF	0.26	1.50	610.72	
R&R Roof vent - turbine type	2.00 EA	7.05	84.18	182.46	
Totals: Rcof				23,829.31	
Total: Exterior				29,815.10	

Interior

		Hall		LxWxH 23'5" x 3'7" x 8'0"
			274.78 SF Walls	83.91 SF Ceiling
Ficons Height	\prec		358.69 SF Walls & Ceiling	83.91 SF Floor
**	san Langto		9.32 SY Flooring	30.42 LF Floor Perimeter
Room Wath			187.33 SF Long Wall	28.67 SF Short Wall
			54.00 LF Ceil. Perimeter	
Missing Wall:	1 -	4'2" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	1 -	3'5" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	1 -	2'6" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	2 -	2'8" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	1 -	2'6" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	1 -	3'0" X 6'8"	Opens into Exterior	Goes to Floor



Subroom 1: Offset 1	LxWxH 3'4" x 2'4" x 8'0"
72 89 SF Walls	7.78 SF Ceiling
80.67 SF Walls & Ceiling	7.78 SF Floor
0.86 SY Flooring	8 67 LF Floor Perimeter
26.67 SF Long Wall	18.67 SF Short Wall
11.33 LF Ceil Perimeter	

Missing Wall: 1 - 2'8" X 6'8"	Opens into Hall			
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Contents - move out then reset	1.00 EA	0.00	44.25	44.25
Clean floor	91.69 SF	0.00	0.23	21.09
R&R Crown molding - 3 1/4"	65.33 LF	0.47	2.81	214.29
R&R Paneling	347.67 SF	0.21	1 84	712.72
R&R Interior door unit	5.00 EA	14.72	175.16	949.40
R&R Door opening (jamb & casing)	5.00 EA	4.95	93.05	49000
Seal & paint crown molding	65.33 LF	0.00	1.02	66.64
Paint the surface area - one coat	40.56 SF	0.00	0.45	18.25
Mask and prep for paint	65.33 LF	0.00	1.05	68.60

Totals: Hall 2,585.24

	Hall Bath		LxWxH 10'9" x 4'3" x 8'0"
\wedge		105.93 SF Walls	45.69 SF Ceiling
Room Height		151.62 SF Walls & Ceiling	45.69 SF Floor
Same / seed		5.08 SY Flooring	20 33 LF Floor Perimeter
Room Watt		86.00 SF Long Wall	34.00 SF Short Wall
		25.33 LF Ceil Perimeter	
	Subroom 1:	Offset 1	LxWxH 8'5" x 2'0" x 4'2"
_	<u></u>	51.74 SF Walls	16.83 SF Ceiling
		68.57 SF Walls & Ceiling	16 83 SF Floor
Room House		1 87 SY Flooring	20.83 LF Floor Perimeter
Roam Width		35.07 SF Long Wall	8.33 SF Short Wall
		20.83 LF Ceil. Perimeter	
Missing Wall: 1	- 8'5" X 4'2"	Opens into Hallway	Goes to neither Floor/Ceiling
	Subroom 2:	Offset 2	LxWxH 5'0" x 2'7" x 6'10"
<u></u>		69.48 SF Walls	12.92 SF Ceiling
RoomHeight		82.39 SF Walls & Ceiling	12.92 SF Floor
Recombends		1.44 SY Flooring	15.17 LF Floor Perimeter
Rosen Width		34 17 SF Long Wall	17.65 SF Short Wall
		15.17 LF Ceil Perimeter	
Missing Wall: 1	- 5'0" X 6'10"	Opens into Hallway	Goes to neither Floor/Ceiling
	Subroom 3:	Closet	LxWxH 2'8" x 2'4" x 8'0"
		63.33 SF Walls	6.22 SF Ceiling
RoonHeight		69 56 SF Walls & Ceiling	6.22 SF Floor
Fragmi andh	>	0.69 SY Flooring	7.50 LF Floor Perimeter
Room Width		21.33 SF Long Wall	18.67 SF Short Wall
		10.00 LF Ceil. Perimeter	
Missing Wall: 1	- 2'6" X 6'8"	Opens into Hallway	Goes to Floor

Room Visual Room Length

Toilet	LxWxH 2'8" x 2'6" x 8'0"
66.00 SF Walls	6 67 SF Ceiling
72.67 SF Walls & Ceiling	6.67 SF Floor
0.74 SY Flooring	7.83 LF Floor Perimeter
21.33 SF Long Wall	20.00 SF Short Wall
10.33 LF Ceil, Perimeter	

Missing Wall:

1 -2'6" X 6'8"


Subroom 4:

Subroom 5: Shower

Opens into Hallway

Goes to Floor

LxWxH 4'8" x 2'6" x 6'9"



11.67 SF Ceiling 65.25 SF Walls 11.67 SF Floor 76.92 SF Walls & Ceiling 9.67 LF Floor Perimeter 1.30 SY Flooring 16.88 SF Short Wall 31.50 SF Long Wall

9.67 LF Ceil. Perimeter

Missing Wall: 1 - 4'8" X 6'9"	Opens into Hallway		Goes to Floor/Ceiling	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Clean floor	99.99 SF	0.00	0.23	23.00
R&R Crown molding - 3 1/4"	91.33 LF	0.47	2.81	299.57
R&R 5/8" drywail - hung, taped, ready for texture	521.72 SF	0.29	1.11	730.41
R&R Door opening (jamb & casing)	1.00 EA	4.95	93.05	98.00
R&R Acoustic ceiling (popcorn) texture	99.99 SF	0.32	0.68	99.99
Seal & paint crown molding	91.33 LF	0.00	1.02	93.16
Paint the walls and ceiling	521.72 SF	0 00	0.45	234.77
Detach & Reset Heat/AC register	1.00 EA	0.00	0.00	7.50
Detach & Reset Light fixture - High grade	2.00 EA	0.00	0.00	55.88
Detach & Reset Bathroom fan, light, and heater	1.00 EA	0.00	0.00	66.55
Detach & Reset l'Inorescent - acoustic grid fixture - two lube, 2 y 4 t	1 00 EA	0.00	0.00	42.16
Clean register - hear / AC	1.00 EA	0.00	4.25	4.25
Clean light fixture	3.00 EA	0.00	5.17	15.51
Clean bathroom fan	1.00 EA	000	13.67	13.67
Mask and prep for paint	91.33 LF	000	1.05	95.90
Totals: Hall Bath		<u> </u>		1,880.32

		Bedroom 2			LxWxH 18'0" x	11'0" x 8'0"
<u> </u>			355.87 SF Walls	<u> </u>	198.00 SF Ceiling	
Hoom Height	3		553.87 SF Walls & Ceil	ing	198.00 SF Floor	
need needs			22.00 SY Flooring	J	46.50 LF Floor Perin	neter
Room Width	arna.		144.00 SF Long Wall		88.00 SF Short Wall	
			53.17 LF Ceil. Perimet	er		
Missing Wall:	2	3'7" X 4'2"	Opens into Exteri	or	Goes to neither Floor	/Ceiling
Missing Wall:	1 -	2'8" X 6'8"	Opens into Exteri		Goes to Floor	
		Subroom 1:	Offset 1		LxWxH 4'10"	x 2'3" x 7'0"
			65.34 SF Walls		10.88 SF Ceiling	
	\geq		76.21 SF Walls & Ceil	ino	10-88 SF Floor	
Ream Haight	<u> </u>		1.21 SY Flooring	8	9.33 LF Floor Peris	meter
Room Wath	xn Lengin		33.83 SF Long Wall		15.75 SF Short Wall	l
			9.33 LF Ceil. Perime	ter		
Missing Wall:	1 -	4'10" X 7'0"	Opens into Bedro	om 2	Goes to Floor/Ceiling	;
		Subroom 2:	Closet		LxWxH 3'0"	x 2'4" x 8'0"
<u></u>			72.00 SF Walls		7.00 SF Ceiling	
Room Horak	\geq		79.00 SF Walls & Cei	ling	7 00 SF Floor	
	mi esta		0.78 SY Flooring	· ·	8.67 LF Floor Peri	meter
Room Width			24.00 SF Long Wall		18.67 SF Short Wal	1
			10.67 LF Ceil. Perime	ter		
Missing Wall:	1 -	2'0" X 6'8"	Opens into Bedro	oom 2	Goes to Floor	
		Subroom 3:	Closet 2		LxWxH 3'0"	x 2'4" x 8'0"
_	_		72.00 SF Walls		7.00 SF Ceiling	
			79.00 SF Walls & Cei	ling	7.00 SF Floor	
-Room Height	com Length		0.78 SY Flooring	5	8.67 LF Floor Peri	meter
Roam Width	an Congre		24.00 SF Long Wall		18.67 SF Short Wal	.1
			10.67 LF Ceil. Perime	eter		
Missing Wall:	1 -	2'0" X 6'8"	Opens into Bedro	oom 2	Goes to Floor	
DESCRIPTION			QNTY	REMOVE	REPLACE	TOTAL
Contents - move	out then	reset	1.00 EA	0.00	44.25	44.25
2225_22ND_ST					11/16/2008	Page: 9

CONTINUED - Bedroom 2

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Clean floor	222.88 SF	0.00	0.23	51.26
R&R 5/8" drywa I - hung, taped, floated, ready for paint	788.08 SF	0.33	1.46	1,410.67
Texture drywall	788.08 SF	0.00	0.66	520.13
R&R Door opening (jamb & casing)	2.00 EA	4.95	93.05	196.00
R&R Crown molding - 3 1/4"	83.83 LF	0.47	2.81	274.96
Seal & paint crown molding	83.83 LF	0.00	1.02	85.51
Mask and prep for paint	83-83 LF	0.00	1.05	88.02

Totals: Bedroom 2 2,670.80

		Master Bath		LxWxH 6'0" x 5'0" x 8'0"
			68.24 SF Walls	30.00 SF Ceiling
Room Height	>]		98.24 SF Walls & Ceiling	30.00 SF Floor
	com Large		3.33 SY Flooring	9.17 LF Floor Perimeter
Room Width			48.00 SF Long Wall	40.00 SF Short Wall
			9.17 LF Ceil Perimeter	
Missing Wall:	1 -	3'7" X 4'2"	Opens into Exterior	Goes to neither Floor/Ceiling
Missing Wall:	1 -	3'0" X 8'0"	Opens into Exterior	Goes to Floor/Ceiling
		Subroom 1:	Offset 1	LxWxH 4'10" x 2'5" x 7'0"
<u> </u>		Subroom 1:	Offset 1 67.67 SF Walls	LxWxH 4'10" x 2'5" x 7'0" 11.68 SF Ceiling
Room Height	\geq	Subroom 1:		
Pours Height	ioun length	Subroom 1:	67.67 SF Walls 79.35 SF Walls & Ceiling	11.68 SF Ceiling
	counterpr	Subroom 1:	67.67 SF Walls	11.68 SF Ceiling 11.68 SF Floor
	contects	Subroom 1:	67.67 SF Walls 79.35 SF Walls & Ceiling 1.30 SY Flooring	11.68 SF Ceiling 11.68 SF Floor 9.67 LF Floor Perimeter

2225_22ND_ST 11/16/2008 Page: 10

LxWxH 5'0" x 1'9" x 7'0"

1,218.36

Cost Control Sevices

Totals: Master Bath

Subroom 2: Offset 2 8.75 SF Ceiling 59.50 SF Walls 8.75 SF Floor 68.25 SF Walls & Ceiling 8 50 LF Floor Perimeter 0.97 SY Flooring 12.25 SF Short Wall 35.00 SF Long Wall


Missing Wall: 1 - 5'0" X 7'0"	Opens into Maste	r Bath	Goes to Floor/Ceiling	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Clean floor	50.43 SF	0.00	0.23	11 60
R&R Crown molding - 3 1/4"	27.33 LF	0.47	2.81	89.65
R&R 5/8" drywail - hung, taped, floated, ready for paint	245.84 SF	0.33	1.46	440.06
Texture drywall	245.84 SF	0.00	0.66	162.25
R&R Door opening (jamb & casing)	3.00 EA	4.95	144.87	449.46
R&R Window trim set (casing & stop)	2.00 LF	0.40	3.98	8.76
Seal & paint crown molding	27.33 LF	000	1.02	27.88
Mask and prep for paint	27.33 LF	0.00	1.05	28.70

8.50 LF Ceil, Perimeter

		Den		LxWxH 15'3" x 13'4" x 8'0"
Room Width	com Length		222.67 SF Walls 426.00 SF Walls & Ceiling 22.59 SY Flooring 122.00 SF Long Wall 39.83 LF Ceil Perimeter	203.33 SF Ceiling 203.33 SF Floor 31.83 LF Floor Perimeter 106.67 SF Short Wall
Missing Wall:	1 -	13'4" X 8'0"	Opens into Exterior	Goes to Floor/Ceiling
Missing Wall:	1 -	4'0" X 8'0"	Opens into Exterior	Goes to Floor/Ceiling
Missing Wall:	1 -	7'6" X 5'4"	Opens into Exterior	Goes to neither Floor/Ceiling

Subroom 1: Offset 1

LxWxH 8'0" x 1'9" x 8'0"



100.00 SF Walls 114.00 SF Walls & Ceiling 1.56 SY Flooring 64.00 SF Long Wall 19.50 LF Ceil, Perimeter

14.00 SF Floor 11.50 LF Floor Perimeter 14.00 SF Short Wall

14.00 SF Ceiling

Missing Wall: 1 - 8'0" X 7'0"	Opens into Den		Goes to Floor	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Contents - move out then reset	1.00 EA	0.00	44.25	44.25
Clean floor	217.33 SF	0.00	0.23	49,99
R&R Crown molding - 3 1/4"	59 33 LF	0.47	2.81	194.61
R&R 1/2" drywa l - hung, taped, ready for texture	540.00 SF	0.29	1.09	745.20
R&R Door opening (jamb & casing)	3.00 EA	4.95	144.87	449.46
R&R Window trim set (casing & stop)	2.00 LF	0.40	3 12	7.04
R&R Batt insulation - 6" - R21	322.67 SF	0.26	0.87	364.61
R&R Acoustic ceiling (popcorn) texture	217.33 SF	0.32	0.68	217.33
Seal & paint crown molding	59.33 LF	0.00	1.02	60.52
Paint the walis and ceiling	540.00 SF	0.00	0.45	243.00
Detach & Reset Ceiling fan & light	1.00 EA	0.00	0.00	99.50
Mask and prep for paint	59.33 LF	0.00	1 05	62.30
Totals: Den				2,537.81

| Second Height | Second Heigh

QNTY	REMOVE	REPLACE	TOTAL
285.83 SF	0.00	0.23	65.74
67.67 LF	0.47	2.81	221.95
	285.83 SF	285.83 SF 0.00	285.83 SF 0.00 0.23

2225_22ND_ST 11/16/2008 Page: 12


CONTINUED - Kitchen

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R 5/8" drywa 1 - hung, taped, floated, ready for paint	827.17 SF	0.33	1.46	1,480 64
R&R Door opening (jamb & casing)	1.00 EA	4.95	93.05	98.00
R&R Window trim set (casing & stop)	1.00 LF	0.40	3.98	4.38
Seal & paint crown molding	67.67 LF	0.00	1.02	69.02
Detach & Reset Fluorescent light fixture	2.00 EA	0.00	0.00	84.32
Detach & Reset Fluorescent - acoustic grid fixture - two τυοε, 2'Σ 4'	2.00 EA	0.00	0.00	84.32
Mask and prep for paint	67.67 LF	0.00	1.05	71.05
				2 170 42

Totals: Kitchen 2,179.42

Breakfast Room

LxWxH 9'9" x 8'5" x 8'0"



132.56 SF Walls
214.62 SF Walls & Ceiling
9.12 SY Flooring
78.00 SF Long Wall
27.33 LF Ceil. Perimeter

82.06 SF Ceiling 82.06 SF Floor 14.42 LF Floor Perimeter 67.33 SF Short Wall

Missing Wall:	1 ~	8'4" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	1 -	4'7" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	1 -	9'0" X 8'0"	Opens into Exterior	Goes to Floor/Ceiling
				 DEDI ACE

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Contents - move out then reset	1.00 EA	0.00	44.25	44.25
Clean floor - tile	82.06 SF	0.00	0.46	37.75
R&R Crown molding - 3 1/4"	27.33 LF	0.47	2.81	89.65
R&R 5/8" drywail - hung, taped, ready for texture	214.62 SF	0.29	1.11	300.47
R&R Batt insulation - 6" - R21	82.06 SF	0.26	0.87	92.73
R&R Acoustic ceiling (popcorn) texture	82.06 SF	0.32	0.68	82.06
Paint the ceiling one coat	82.06 SF	0.00	0.45	36.93
225_22ND_ST			11/16/2008	Page: 1

CONTINUED - Breakfast Room


DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Seal & paint crown molding	27.33 LF	0.00	102	27.88
Mask and prep for paint	27.33 LF	0.00	1.05	28.70
Totals: Breakfas: Room				740.42

Rear Hal	Ì		LxWxH 9'6''	x 4'4" x 8'0"
	115.56 SF Walls		41.17 SF Ceiling	
Room Height	156.72 SF Walls & Ceiling		41.17 SF Floor	
RoonLength	4.57 SY Flooring		12.67 LF Floor Peri	imeter
Room Width	76.00 SF Long Wall		34.67 SF Short Wal	11
	23.33 LF Ceil. Perimeter			
Missing Wall: 2 - 3'0" X 6'8"	Opens into Exterior		Goes to Floor	
Missing Wall: 1 - 2'0" X 6'8"	Opens into Exterior		Goes to Floor	
Missing Wall: 1 - 2'8" X 6'8"	Opens into Exterior	erior Goes to Floor		
Missing Wall: 1 - 4'4" X 8'0"	Opens into Exterior			
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Contents - move out then reset	1.00 EA	0.00	44.25	44,25
Clean floor	41.17 SF	0.00	0.23	9.47
R&R 5/8" drywail - hung, taped, floated, ready for paint	156.72 SF	0.33	1.46	280.53
R&R Door opening (jamb & casing)	3.00 EA	4.95	93.05	294.00
	23.33 LF	0.47	2.81	76.53
R&R Crown molding - 3 1/4"		0.00 1.02 23.8		
R&R Crown molding - 3 1/4" Seal & paint crown molding	23.33 LF	0.00	1.02	23.80

	Utility / Bath	Room	LxWxH 8'11" x 3'5" x 8'0"
\wedge		28.67 SF Walls	30.47 SF Ceiling
From Height		59.13 SF Walls & Ceiling	30.47 SF Floor
Room Lengto		3.39 SY Flooring	2.25 LF Floor Perimeter
Room Width		71.33 SF Long Wall	27.33 SF Short Wall
		10.25 LF Ceil. Perimeter	
	Subroom 1:	Closet	LxWxH 6'6" x 3'5" x 8'0"
		118.67 SF Walls	22.21 SF Ceiling
Room Heide		140.88 SF Walls & Ceiling	22.21 SF Floor
Pomi enth		2.47 SY Flooring	13.83 LF Floor Perimeter
Room With		52.00 SF Long Wall	27.33 SF Short Wall
		19.83 LF Ceil. Perimeter	
Missing Wall: 1 -	6'0" X 6'8"	Opens into Utility / Bath Room	Goes to Floor
	Subroom 2:	Closet 2	LxWxH 3'0" x 2'6" x 8'0"
\wedge		74.67 SF Walls	7.50 SF Ceiling
Room Height		82.17 SF Walls & Ceiling	7.50 SF Floor
RoomLeagth		0.83 SY Flooring	9.00 LF Floor Perimeter
Room West		24.00 SF Long Wall	20.00 SF Short Wall
		11 00 LF Ceil. Perimeter	
Missing Wall: 1 -	2'0" X 6'8"	Opens into Utility / Bath Room	Goes to Floor
	Subroom 3:	Dressing Room	LxWxH 6'10" x 4'4" x 8'0"
\wedge		124.67 SF Walls	29.61 SF Ceiling
Room Height		154.28 SF Walls & Ceiling	29.61 SF Floor
RoomLength		3.29 SY Flooring	15 58 LF Floor Perimeter
Roan Wight		54.67 SF Long Wall	34.67 SF Short Wall
		15.58 LF Ceil. Perimeter	
Missing Wall: 1 -	3'4" X 8'0"	Opens into Utility / Bath Room	Goes to Floor/Ceiling
		•	

Subroom	4:	Offset	1
---------	----	--------	---

LxWxH 8'5" x 7'0" x 8'0"



185 33 SF Walls
244.25 SF Walls & Ceiling
6.55 SY Flooring
23.17 LF Floor Perimeter

58.92 SF Ceiling
58.92 SF Floor
23.17 LF Floor Perimeter
56.00 SF Short Wall
23.17 LF Ceil, Perimeter


Missing Wall: 1 - 3'4" X 8'0" Missing Wall: 1 - 4'4" X 8'0"	Opens into Utility / Bath Room Opens into Utility / Bath Room		Goes to Floor/Ceiling Goes to Floor/Ceiling	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Clean floor - tile	148.70 SF	0.00	0.46	68.40
R&R Crown molding - 3 1/4"	79.83 LF	0.47	2.81	261.84
R&R 5/8" drywa'l - hung, taped, ready for texture	680.70 SF	0.29	1.11	952.98
Texture drywall	680.70 SF	0.00	0.66	449.26
R&R Batt insulation - 6" - R21	11.00 SF	0.26	0.87	12.43
R&R Acoustic ceiling (popcorn) texture	148.70 SF	0.32	0.68	148.70
Paint the ceiling	148.70 SF	0.00	0.67	99.63
Seal & paint crown molding	79.83 LF	0.00	1.02	81.43
Mask and prep for paint	79.83 LF	0.00	1.05	83.82

Totals: Utility / Bath Room 2,158.49

		Garage		LxWxH 22'3" x 20'4" x 8'0"
Room Height Room Width Room Largth			521.32 SF Walls 973.74 SF Walls & Ceiling 50.27 SY Flooring 178.00 SF Long Wall 85.17 LF Ceil. Perimeter	452.42 SF Ceiling 452.42 SF Floor 61.83 LF Floor Perimeter 162.67 SF Short Wall
Missing Wall: Missing Wall:	1 - 1 -	3'0" X 6'8" 17'10" X 6'11"	Opens into Exterior Opens into Exterior	Goes to Floor Goes to Floor

Subroom 1: Closet

LxWxH 4'8" x 3'10" x 8'0"



119.33 SF Walls
137.22 SF Walls & Ceiling
1.99 SY Flooring
1.99 SY Flooring
14.50 LF Floor Perimeter
37.33 SF Long Wall
17.00 LF Ceil, Perimeter

Missing Wall: 1 - 2'6" X 6'8"	Opens into Garage		Goes to Floor	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Contents - move out then reset	1.00 EA	0.00	44.25	44.25
Clean floor	470.31 SF	0.00	0 23	108.17
R&R 5/8" drywa'l - hung, taped, floated, ready for paint	1,110.96 SF	0.33	1.46	1,988.62
Texture drywall	1,110.96 SF	0.00	0.66	733.23
R&R Door opening (jamb & casing)	3.00 EA	4.95	144.87	449.46
R&R Crown molding - 3 1/4"	102.17 LF	0.47	2.81	335 12
Seal & paint crown molding	102.17 LF	0.00	1.02	104.21
Mask and prep for paint	102 17 LF	0.00	1.05	107.28

Totals: Garage 3,870.34

Dining Room LxWxH 12'4" x 10'3" x 8'0" 296 00 SF Walls 126.42 SF Ceiling 422.42 SF Walls & Ceiling 126.42 SF Floor 14.05 SY Flooring 37.00 LF Floor Perimeter 98.67 SF Long Wall 82.00 SF Short Wall 37.00 LF Ceil Perimeter

Missing Wall: 1 - 5'4" X 8'0" Missing Wall: 1 - 2'10" X 8'0" DESCRIPΤΙΘΝ		Opens into Exterior Opens into Exterior		Goes to Floor/Ceiling Goes to Floor/Ceiling		
		QNTY	REMOVE	REPLACE	TOTAL	
Contents - move out then reset		1.00 EA	0.00	44.25	44.25	
Clean floor		126.42 SF	0.00	0.23	29.08	
R&R 5/8" drywa-1 - hung, taped, floated, ready for paint		422.42 SF	0.33	1.46	756.13	

2225_22ND_ST 11/16/2008 Page: 17

CONTINUED - Dining Room

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Texture drywall	422.42 SF	0.00	0.66	278.80
R&R Crown molding - 3 1/4"	37.00 LF	0.47	2.81	121.36
Seal & paint crown molding	37.00 LF	0.00	1.02	37.74
Totals: Dining Room				1,267.36
Total Interior	12.3			21,861.64
Line Item Subtotals: 2225_22ND_ST				96,362.13
Adjustments for Base Service Charges				Adjustment
Carpenter - Finish, Trim/Cabinet				113.16
Carpenter - General Framer				88.32
Cleaning Technician				47.00
Floor Cleaning Technician				56.66
Drywall Installer/Fit/isher				178.60
Electrician				126.40
Heating / A.C. Mechanic				120.06
Insulation Installer				90.94
General Laborer				24.20
Painter				102.54
Roofer				189.90
Siding Installer				110.76
Total Adjustments for Base Service Charges:				1,248.54
Line Item Totals: 2225_22ND_ST				97,610.67

Grand Total Areas:

5,642 02	SF Walls	1,836.81	SF Ceiling	7,478 83	SF Walls and Ceiling
•	SF Floor	204.09	SY Flooring	719.09	LF Floor Perimeter
•	SF Long Wall	2,698.36	SF Short Wall	850.01	LF Ceil. Perimeter
0.00	Floor Area	0.00	Total Area	0.00	Interior Wall Area
0 00	Exterior Wall Area	0.00	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

Summary for Dwelling

Line Item Total Total Adjustments for Base S	Service Charges	3		96,362.13 1,248.54
Subtotal Overhead Profit Material Sales Tax	@ @ @	10.0% x 10.0% x 9.000% x	97,610.67 107,371.74 25,469.87	97,610.67 9,761.07 10,737 17 2,292.29
Replacement Cost Value Net Claim				\$120,401.20 \$120,401.20

Tommy Greenlee

2225_22ND_ST 11/16/2008 Page: 20

Recap by Room

Estima	te: 2225_22ND_ST	44 <05 30	45.78%
	General Conditions	44,685.39	43,/679
Area:	Exterior		4 5 5 6 /
	Front Elevation	1,517.44	1.55%
	Right Elevation	371.95	0.38%
	Rear Elevation	3,517.50	3.60%
	Left Elevation	578.90	0.59%
	Roof	23,829.31	24.41%
-	Area Subtotal: Exterior	29,815.10	30.54%
Area:	Interior		
	Hall	2,585.24	2.65%
	Hall Bath	1,880.32	1.93%
	Bedroom 2	2,670.80	2.74%
	Master Bath	1,218.36	1.25%
	Den	2,537.81	2.60%
	Kitchen	2,179.42	2.23%
	Breakfast Room	740.42	0.76%
	Rear Hall	753.08	0.77%
	Utility / Bath Room	2,158.49	2.21%
	Garage	3,870.34	3.97%
	Dining Room	1,267.36	1.30%
-	Area Subtotal: Interior	21,861.64	22.40%
Subtot	cal of Areas	96,362.13	98.72%
Base S	ervice Charges	1,248.54	1.28%
Total		97,610.67	100.00%

Recap by Category

O&P Items			Total Dollars	%
CLEANING	<u></u>		508.98	0.42%
CONTENT MANIPULATION			309.75	0.26%
GENERAL DEMOLITION			20,088.15	16.68%
DOORS			875.80	0.73%
DRYWALL			9,862.62	8.19%
ELECTRICAL			66.55	0.06%
PERMITS AND FEES			1,000.00	0.83%
FINISH CARPENTRY / TRIMWORK			5,129.41	4.26%
FRAMING & ROUGH CARPENTRY			9,772.73	8.12%
HEAT, VENT & AIR CONDITIONING			7,970.10	6.62%
INSULATION			2,336.68	1.94%
LABOR ONLY			19,694.40	16.36%
LIGHT FIXTURES			414.11	0.34%
PANELING & WOOD WALL FINISHES			639.71	0.53%
PAINTING			3,086.81	2.56%
SWIMMING POOLS & SPAS			2,913.60	2,42%
ROOFING			7,745.87	6.43%
SOFFIT, FASCIA, & GUTTER			322.88	0.27%
TEMPORARY REPAIRS			3,623.98	3.01%
Subtotal			96,362.13	80.03%
Base Service Charges			1,248.54	1.04%
Overhead	@	10.0%	9,761.07	8.11%
Profit	<u>@</u>	10.0%	10,737.17	8.92%
O&P Items Subtotal			118,108.91	98.10%
Material Sales Tax	@	9.000%	2,292.29	1.90%
Total			120,401.20	100.00%

Case 2:07-cv-01990-PM-KK Document 32-4 Filed 02/23/09 Page 26 of 31

Cost Control Services

Cliens

Harmon, Ella

Property"

2225 22 ND Street

Lake Charles, LA 70601

Operator Info:

Operator:

TOMMY

Type of Estimate:

Wind Damage

Date Entered

11/16/2008

Date Assigned:

Price Lis:

LALC2B53

Restoration/Service/Remodel


Estimate:

LA-22**25-22ND-COV-B**

LA-2225-22ND-COV-B


Exterior

Fencing



DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R Post & rail feace	85 00 LF	3.46	9.13	1,070.15
Totals: Fencing				1,070.15

Shed



LA-2225-22ND-COV-B

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R Storage shed - Metal / Damaged by fallen tree	1.00 EA	117 78	905.19	1,022.97
Totals: Shed				1,022.97
Total: Exterior				2,093 12
				2 2 2 2 2 2
Line Item Subtotals: LA-2225-22ND-COV-B				2,093.12
Line Item Subtotals: LA-2225-22ND-COV-B Adjustments for Base Service Charges				2,093.12 Adjustment
Adjustments for Base Service Charges Carpenter - Mechanic				ŕ
Adjustments for Base Service Charges Carpenter - Mechanic Fencing Installer				Adjustment
				Adjustment 115.58 96.18

Grand Total Areas:

0.00	SI Walls	0.00	SF Ceiling	0.00	SF Walls and Ceiling
0.00	SF Floor	0.00	SY Flooring	0.00	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	000	LF Ceil Perimeter
0.00	Floor Area	0.00	Total Area	0.00	Interior Wall Area
0.00	Exterior Wall Area	0.00	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
	Total Ridge Length	0.00	Total Hip Length		

LA-2225-22ND-COV-B 11/16/2008 Page: 3

Summary

ervice Charges	S		2,093.12 211.76
			2,304.88
@	10.0% x	2,304.88	230.49
-	10.0% x	2,535.37	253.54
<u>@</u>	8.250% x	884.57	72.98
			\$2,861.89
			\$2,861.89
	@	@ 10.0% x	@ 10.0% x 2,304.88 @ 10.0% x 2,535.37

LA-2225-22ND-COV-B 11/16/2008 Page: 4

Recap by Room

Estimate: LA-2225-22ND-COV-B

Area: Exterior Fencing Shed	1,070.15 1,022.97	46.43% 44.38%
Area Subtotal: Exterior	2,093.12	90.81%
Subtotal of Areas	2,093.12	90.81%
Base Service Charges	211.76	9.19%
Total	2,304.88	100.00%

PCL XL error

Subsystem: xlparse

Error: Input Stream EOF

Operator: Parser
Position: 2206